

March 17, 2014

Caliber Energy Systems Partnership
10497 - 92nd Street
High Level, Alberta
T0H 1Z0

Equipment Certification

Rig No.:	N/A
Equipment:	IR Slip Type Elevator
Model:	MYT - 40 Ton c/w Slip Assembly
Customer P.O.:	N/A
Serial No.:	CE05-02
Inspection Report No.:	H-22189
Alco Sales/Engineering No.:	40321-E
APEGGA Permit to Practice No.:	P10702
Alco Shop Work Order # :	31895

The above-mentioned elevator required a Level IV inspection (as per Canadian Association of Oilwell Drilling Contractors, R.P. 4.0), applicable repairs, and certification for service.


A magnetic particle (MT) inspection was conducted on Mar 03, 2014, after the elevator was completely disassembled and sandblasted.

Repair procedures were developed based on the MT inspection report as well as a thorough visual examination performed by qualified personnel with Alco Inc.

Based on the final inspection on Mar 17, 2014, after load testing, it is our opinion that the elevator is a safe operating unit and may be returned to service within the manufacturer's original rating and specification.

This certification is valid for a period of 6 years from the date indicated on the engineer's stamp shown below, as per the recommendations provided by the Canadian Association of Oilwell Drilling Contractors, or until the elevator has been damaged either as a result of operation, transportation or handling.





**ALCO HYDRA
OIL TOOL**

CUSTOMER CAUBER ENERGY
 W/O# 40321
 CUST. ID# CE5-0A
 DATE 11/11/11
 MINIMUM HOLD TIME 5 MIN
 LOAD TESTED TO 60 TON INSP# 22189
 LOAD TEST SERIAL 031518171819202122
 EQUIPMENT TESTED IR 40 TON M/T E/LEN
 CSI-1575

15 MIN.

567
511
453
393
336
277 TONS
220
165
106
49

1.25 2.5 3.75 5 6.25 7.5 8.75 10 11.25 12.5 13.75

49
106
165
220
277 TONS
336
393
453
511
567