

October 13, 2011

Viper Rentals + Service Ltd.  
10709 - 95 Street  
High Level, Alberta  
T0H 1Z0

---

**Equipment Certification**

**Rig No.:** N/A  
**Equipment:** AOT Tubing Elevator  
**Model:** 2 3/8" - 90° - TA 100 Ton  
**Customer P.O.:** N/A  
**Serial No.:** VRS-1716  
**Inspection Report No.:** H-26898  
**Alco Sales/Engineering No.:** 15840-E  
**APEGGA Permit to Practice No.:** P10702  
**Alco Shop Work Order # :** 13515

---

The above-mentioned elevator required a Level IV inspection (as per Canadian Association of Oilwell Drilling Contractors, R.P. 4.0), applicable repairs, and certification for service.

A magnetic particle (MT) inspection was conducted on August 10, 2011, after the elevator was completely disassembled and sandblasted.

Repair procedures were developed based on the MT inspection report as well as a thorough visual examination performed by qualified personnel with Alco Inc.

Based on the final inspection on October 13, 2011, after load testing, it is our opinion that the elevator is a safe operating unit and may be returned to service within the manufacturer's original rating and specification.

This certification is valid for a period of 6 years, as per the recommendations provided by the Canadian Association of Oilwell Drilling Contractors, or until the elevator has been damaged either as a result of operation, transportation or handling.

